



4119 White Bear Parkway, St. Paul, MN 55110 USA
Phone (651) 429-1100, Fax (651) 429-1122
Toll Free (800) 4-CORTEC, E-mail info@corotecvci.com
Internet http://www.corotecvci.com

Testing Water Based Rust Preventatives on Machined Steel

From: Cortec Corporation Laboratories
4119 White Bear Parkway
St. Paul, MN 55110

cc: Boris Miksic
Mike Gabor
Cliff Cracauer
Jessica Carpenter

Project #: 13-069-1825.bis

Test conducted by:

A handwritten signature in black ink that reads "Caleb Pheneger".

Caleb Pheneger
Technical Service Engineer

Approved by:

A handwritten signature in black ink that reads "M. Kharshan".

Margarita Kharshan
Laboratory Director

Date: May 3, 2013



Background: The customer wants to compare VpCI-379 to a competitor water based rust preventative on highly polished, machined steel parts.

Samples Received:

- 3 steel parts approximately 3 inches in diameter
- ChemCheq 6021C

Method: ASTM D-1748 modified (120 °F and ~99% relative humidity)

Materials: Metal Test Samples
ChemCheq 6021C
VpCI-379 (03303)

Procedure: The following procedure was used:

- 1) Laboratory grade methanol was applied to the parts and wiped off with a lint free wipe.
- 2) Parts were coated with the following products:
 - a. VpCI-379 at 5% concentration in water
 - b. ChemCheq 6021C as received
 - c. Uncoated (Control)
- 3) All parts were left to dry for 24 hours and then placed in a non-VCI polyethylene bag.
- 4) Then each part was placed in the humidity chamber at 120 °F and ~99% relative humidity.
- 5) Parts were monitored for visual corrosion and removed after 360 hours to be photographed.

Results:

ASTM D 1748 Modified	
Treatment	Time Until Failure
None (Control)	< 24 hours
VpCI-379 (5%)	336 hours
ChemCheq	144 hours

Interpretations:

VpCI-379 provided much better corrosion protection than ChemCheq 6021C. After only 144 hours there were 3 spots of corrosion on the part treated with ChemCheq 6021C, while this did not occur until 336 hours with VpCI-379. Additionally, all of the rust spots on VpCI-379 were at the location the non-VCI bag was directly in contact with the metal. This may have pulled the coating off of the part and trapped water on the metal surface.

Photos:

After 360 hours in ASTM D-1748 Modified

