



CASE HISTORY

Refurbishing Tennis Club's Infrastructure



DATE
2011



CUSTOMER
Longboat Key Tennis Center

LOCATION
Longboat Key, Florida

PRODUCTS
CorrVerter®
VpCI®-386 Black



PROBLEM
The steel structures of the Longboat Key Tennis Center showed excessive pitting caused by constant exposure to the tropical Florida climate in proximity to the Gulf of Mexico; and regular watering using recycled water with a high sulfur content.

APPLICATION
The structures were wire brushed to remove loose rust and dirt particles. Cortec's CorrVerter® was then applied, followed by a top coat of VpCI®-386 Black at a DFT of 4 mils (100 microns).

CONCLUSION
Cortec's protection system proved to be cost effective, provided effective corrosion protection for years to come, and most importantly for the management of Longboat Key Tennis Center, was environmentally friendly and safe for their workers.

4119 White Bear Parkway, St. Paul MN 55110 USA
Phone (651)429-1100, Toll free (800) 4-CORTEC
Fax (651) 429-1122, Email: info@cortecvci.com
www.cortecvci.com

ch405 10/2011 Page 1 of 2

Printed on recycled paper 100% Post Consumer



©2011, Cortec Corporation. All Rights Reserved. Copying of these materials in any form without the written authorization of Cortec Corporation is strictly prohibited. ISO Accreditation applies to Cortec's processes only.

